

S/027/023

Division of Oil, Gas, & Mining
Mining Report

04/04/95

MINE ID: S0270023

MINE NAME: POTTED ROCK #12 AND #9

OPERATOR: GREAT BASIN CONSTRUCTION
CONTACT: ROBERT B THOMAS
ADDRESS: 3620 WEST 6500 NORTH
DELTA UT 84624

PHONE: (801)864-4444

Surface Owner: BLM
Mineral Owner: BLM

BLM #: UTU-070609
Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr2	Qtr2	Sec	Town	Range
NW	SW					11	16.0S	9.0W
NW	SW		NW	NW		7	14.0S	8.0W
						16	16.0S	9.0W

Permit Status: NAP

Mine Type [(S)urface, (U)nderground]: S

Mine Status: SUS

Acreage: 0

Status Date: / /

Minerals Mined
DECORATIVE ROCK

DATE
RECEIVED

TENTATIVE APPROVAL
DATE

FINAL APPROVAL
DATE

LAST INSPECTED

04/09/90

/ /

/ /

/ /

BOND TYPE: N/A

BOND AMOUNT:

ANNUAL REPORT YEAR: 94

	YTD	Total	DATE ISSUED:	DATE RESOLVED:
NONCOMP NOTICES:	0	0	/ /	/ /
VIOLATIONS:	0	0	/ /	/ /
REVISIONS:	0	0	/ /	/ /
AMENDMENTS:	0	0	/ /	/ /

COMMENTS:

NOTICE SENT TO THE BLM, APRIL, 1990. OPERATOR REQUESTED PERMISSION TO IMPROVE EXISTING ROAD, AND PERHAPS EXTEND IT ANOTHER MILE. BLM MAY NOT HAVE APPROVED THIS REQUEST. NEED TO FOLLOW UP WITH BLM ON STATUS. 1991 ANNUAL REPORT STATED THAT NO DISTURBANCE WAS MADE BY THIS COMPANY, SO NO RECLAMATION IS NEEDED. BLM INSPECTED SITE 2/3/95 & FOUND NO FURTHER RECLAMATION NEEDED. BLM CLOSED FILE; THEREFORE, DOGM WILL ALSO CLOSE FILE AS IT IS LOCATED ON BLM MANAGED LANDS. INSPECTION NEEDS TO BE MADE.(CHECK SECTIONS BEFORE CLOSE)